

SHOP NOTES King Midget Maintenance and Restoration



This car has its original hood and dash. Note the smooth curve of the top of the grille, with the crown behind it smoothed back to the center ridge. Hard to replicate. This is also an original dash, made of brown leather-textured hardboard, which deteriorated easily.



Tabs and spot welds secure the grille panel.

Detail of dashboard texture.



Red rubber handle on E-brake. Rubber floor mat.

Beige canvas top should tuck in better at front corner.



Original tops did not have center strip.

Correct seat colors and door pull. ■



A. Identification